

TCLK Infrastructure - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated
23813	Bug	Assigned	Normal	System time occasionally jumps ahead by a second when using IP-UCD	Richard Neswold	12/30/2019 12:51 PM
20304	Bug	New	Normal	libpmctrig-3.2 seems to cause failures on NBPMOV	Richard Neswold	07/11/2018 03:28 PM
20113	Feature	Assigned	Normal	Support the extended clock specification	Richard Neswold	06/07/2018 10:45 AM
19689	Bug	Assigned	Normal	UCD timestamps only work for 15 Hz configurations	Richard Neswold	05/01/2018 03:04 PM
19688	Bug	Assigned	Normal	Sync event isn't last in multicast packet	Richard Neswold	04/13/2018 04:42 PM